

02/02/2005 16:13 FAX 650 838 4350

PERKINS COIE

003

Attorney Docket No. 59472-8809.US00

**In the Drawings:**

Please replace Figure 7 with the enclosed replacement sheet, Figure 7.

[59472-8809/BY050330.072]  
Serial No. 10/047,772

2

Examiner: Nguyen, J.  
Art Unit: 2674

PAGE 3/6 \* RCVD AT 2/2/2005 6:07:07 PM [Eastern Standard Time] \* SVR:USPTO-EFXRF-1/1 \* DNIS:8729306 \* CSID:650 838 4350 \* DURATION (mm:ss):01:24

Attorney Docket No. 59472-8809.US00

Remarks

Applicants thank the Examiner for recent telephone conversations, in which Figure 7 and corresponding text was discussed. After the telephone conversations, Applicants submitted a proposed replacement Figure 7 to the Examiner. After further discussion, the Examiner indicated that the proposed replacement figure was acceptable with an additional correction to the connection between capacitor 58 and Gate 2. Accordingly, Applicants submit herewith a revised replacement Figure 7 which has been amended to conform with the text in the specification. Accordingly, no new matter is added by this amendment.

Changes made to the drawing include the previously described connection between capacitor 58 and gate 2, and connections between capacitor 32 and gate 1 and between capacitor 46 and gate 1. These changes conform the figure to the written description. Applicants submit that these changes are submitted to correct an error, and that no deceptive intent was present.

The replacement figure is being provided by facsimile transmission. If a copy is desired or required to be provided by another method, such as mailing, please contact the undersigned to arrange for this.

Attorney Docket No. 59472-8809.US00

If the Examiner believes that a conference would be of value in expediting the prosecution of this application, the Examiner is cordially invited to telephone the undersigned counsel at (650) 838-4300 to arrange for such a conference.

No fees are believed to be due, however, the Commissioner is authorized to charge any underpayment in fees to Deposit Account No. 50-2207, including any funds necessitated due to an accompanying check being drawn on an account with insufficient funds.

Respectfully submitted,  
Perkins Coie LLP

Date: February 2, 2005

  
Glenn E. Von Tersch  
Registration No. 41,364

Correspondence Address:

Customer No. 25096  
Perkins Coie LLP  
P.O. Box 1247  
Seattle, Washington 98111-1247  
(206) 359-8000